

838<sup>97</sup>











Fig. 3.



rising & falling movement  
in front of bar B through crank  
connection. 3

Given three distinct steps in its  
forward movement  
1. Advances font and  
required position on grid for  
dipped ornament after being  
2. After slight retrograde  
movement and dial  
bring font and a  
little short of original  
position and remain there  
during decorative  
3. Now close  
font and  
W.



Fig. 4.

Fig 4

(4 SHEETS)  
SHEET 4.

